History of Road / Lane / Circle From ..... To .....

Year 1	Name of Work 2	Sanctioned Estimate amount and year 3	Period of Execution 4	Particulars of the work done 5	Name of the Contractor 6	Expenditure booked 7	J.E. / A.E. incharge 8	Road cutting done since the work done 9	Remarks should include any special features affecting the road surface) 10
2014-2015	Constr of drain and providing cover slab in Rajthagara Layout in Ward No.09								
	C009-14-0000557	2013-14	2014-15	(1) Re drain at the R/s of Road from RWD-TOW ಕಛೇರಿ thindlu Circle . 109.50mb				—	
				(2) Existing drain	Cover slab -	45 mb.	ಶಿಥಿಲಗೊಂಡಿದೆ		
					KRIDL	1466594-00		ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು. ಪೂರ್ವವಲಯ ಉಪ ವಿಭಾಗ, ಯಲಹಂಕ ವಲಯ, ಬೃ. ಬೆಂ. ಮ. ಪಾ., ಬೆಂಗಳೂರು-97. 3/01/15		

8th main - Road (Thindlu Road)

ROAD REGISTER

Road from Vidyaranyapura main - Road **To** Thindlu circle **Year 20**.....

Length or dia of the Circle	Width at every convenient meters	Nature of existing surface	Curb Chainages	FOOT PATH				Particulars of shoulder drains and their Nos. separately for Left & Right sides	Check drains	Existence of service lines Tel. & Cable UGD line WS line etc.	Date of inspection & the initials	Remarks
				Gravel	B.S. Slab	Concrete	Other Surface					
1	2	3	4	5	6	7	8	9	10	11	12	13
990m	12.00	Asphalt Rufuce	-	-	-	-	-	-	-	W/S and UGD line	25/10/2013	
	10.00											

History of Road / Lane / Circle From To